CITY OF BIRCHWOOD VILLAGE
SUMP INSPECTION REPORT

	WEST OF ELM	2'		YES	4/28/13		OK
	165 WILDWOOD	0		YES	4/28/13		OK
	HOCKEY RINK	4 1/2		No	4/28/13		OK

Id Number	Location:	Depth Below Outlet Pipe*:		Cleaning Required (yes or no):	Date of ~~READING~~	Material Removed**:	Condition of Structure/Maintenance Needed:
4	West of Birch Easement	2'		YES	4/28/13		OK
5	At Birch Easement	2'		YES	4/28/13		OK
11	At Elm Easement	2'		YES	4/28/13		OK
10	East of Elm Easement	6"		YES	4/28/13		OK
15	North end of Tighe Schmitz Park	4'		No	4/28		OK
13	Cedar Street and Hall Avenue	1 1/2'		YES	4/28		OK
20	West side of Grotto Street and Wildwood	3 1/2'		No	4/28		OK

Change from prior reading

*Depth below outlet pipe should be measure as the distance from the bottom of the outlet pipe to the top level of any sediment in the structure. All sumps have four foot depths. 60% Capacity has been reached or exceeded when measurement is 19-inches or less.

**Material removed calculated in cubic yards with depth below outlet pipe in inches: 1.86 – (0.039 x Depth below Outlet Pipe)

INSPECTED BY: KEN JOHNSON

DATE: 4/28/13

[redacted]